

IQ PANEL 2 & 2 PLUS - 2.3.4 SOFTWARE UPDATE - RELEASE NOTES AND INSTRUCTIONS

TSB #: 190731

DATE: 07/31/19

RE: IQ PANEL 2 & 2 PLUS - 2.3.4 SOFTWARE UPDATE
RELEASE NOTES & UPDATE INSTRUCTIONS

Release Notes:

Fixes/Improvements:

- Includes all fixes and improvements from the IQ Panel 2 & 2 Plus 2.3.3 Software Update (<https://dealers.qolsys.com/wp-content/uploads/2019/05/TSB-190508-233-Update.pdf>)
- Includes all fixes and improvements from the 80.25 PowerG Modem Firmware Update (<https://dealers.qolsys.com/wp-content/uploads/2019/06/TSB-190621-80.25-PowerG-Update.pdf>)
- Pin change to better recognize the PowerG daughter card upon reboot

Update Instructions:

Compatibility Note: Your IQ Panel must be on software version 2.0.1 or higher and connected to Wi-Fi to install this update wirelessly.

- 1- Swipe down from the top of the screen and touch "Settings"
- 2- Touch "Advanced Settings"
- 3- Enter a valid installer code (default is 1111)
- 4- Touch "Upgrade Software"
- 5 -Touch "Patch Tag" and enter the patch *iqpanel2.3.4* then touch OK
- 6- Touch "Upgrade Using Network" (panel must be connected to Wi-Fi). Update will download and install
- 7- Once complete touch "OK" to reboot the panel. **DO NOT TOUCH THE SCREEN.** The update process will take approximately 5 minutes. After the panel reboots the home screen will appear and the LED will turn green.

For more information visit: <https://login.qolsys.com/software-downloads/> or email: techsupport@qolsys.com